


# Superconducting magnets for Accelerators

*Martin N Wilson (Rutherford Lab  $\Rightarrow$  Oxford Instruments  $\Rightarrow$  CERN  $\Rightarrow$  consultant)*

## Outline

- why bother with superconductivity?
- properties of superconductors: critical field, temperature & current density
- magnetic fields and how to create them
- load lines, training and how to cure it
- screening currents and the critical state model
- fine filaments, composite wires & cables
- magnetization, field errors & ac losses
- quenching and protection
- hardware
- where to get more info



# *Superconducting magnets for Accelerators*

## *Who needs superconductivity anyway?*

### **Abolish Ohm's Law!**


- no power consumption  
(although do need refrigeration power)
- high current density  $\Rightarrow$  compact windings, high gradients
- ampere turns are cheap, so we don't need iron  
(although often use it for shielding)

### **Consequences**

- lower power bills
- higher magnetic fields mean reduced bend radius
  - $\Rightarrow$  smaller rings
  - $\Rightarrow$  reduced capital cost
  - $\Rightarrow$  new technical possibilities  
(eg muon collider)
- higher quadrupole gradients
  - $\Rightarrow$  higher luminosity




# The critical surface of niobium titanium



- Niobium titanium **NbTi** is the standard ‘work horse’ of the superconducting magnet business
- it is a ductile alloy
- picture shows the **critical surface**, which is the boundary between superconductivity and normal resistivity in 3 dimensional space
- superconductivity prevails everywhere below the surface, resistance everywhere above it
- we define an upper critical field  **$B_{c2}$**  (at zero temperature and current) and critical temperature  **$\theta_c$**  (at zero field and current) which are characteristic of the alloy composition
- critical current density  **$J_c(B, \theta)$**  depends on processing


# The critical line at 4.2K



- because magnets usually work in boiling liquid helium, the critical surface is often represented by a curve of current versus field at 4.2K
- niobium tin Nb<sub>3</sub>Sn has a much higher performance in terms of critical current field and temperature than NbTi
- but it is brittle intermetallic compound with poor mechanical properties
- note that both the field and current density of both superconductors are way above the capability of conventional electromagnets




# Filamentary composite wires




- for reasons that will be described later, superconducting materials are always used in combination with a good normal conductor such as copper
- to ensure intimate mixing between the two, the superconductor is made in the form of fine filaments embedded in a matrix of copper
- typical dimensions are:
- wire diameter = 0.3 - 1.0mm
- filament diameter = 5 - 50 $\mu$ m
- for electromagnetic reasons, the composite wires are twisted so that the filaments look like a rope

# *Fields and ways to create them: conventional*

- iron yoke reduces magnetic reluctance
  - $\Rightarrow$  reduces ampere turns required
  - $\Rightarrow$  reduces power consumption
- iron guides and shapes the field




**BUT iron saturates at ~ 2T**




*Iron electromagnet  
– for accelerator, HEP experiment  
transformer, motor, generator, etc*

# Fields and ways to create them: superconducting dipoles


simplest winding  
uses racetrack  
coils




'saddle' coils make  
better field  
shapes



special winding cross  
sections for good  
uniformity



- some iron - but field shape is set mainly by the winding
- used when the long dimension is transverse to the field, eg accelerator magnets
- known as *dipole* magnets (because the iron version has 2 poles)



LHC has  
'up' & 'down'  
dipoles side by side



# Dipole Magnets



- made from superconducting cable
- winding must have the right cross section
- also need to shape the end turns






# Fields and ways to create them: superconducting quadrupoles

- gradient fields produce focussing
- quadrupole windings



$$B_x = ky$$


$$B_y = kx$$




# Engineering current density

engineering current density  $J_{eng} = J_{sup} \times \text{dilution}$

dilution (by copper, insulation, structure)  $\sim 33\%$




$$J_e = 375 \text{ Amm}^{-2}$$




$$9.5 \times 10^5 \text{ Amp turns}$$

$$= 1.9 \times 10^6 \text{ A.m per m}$$



LHC dipole



$$J_e = 37.5 \text{ Amm}^{-2}$$



$$9.5 \times 10^6 \text{ Amp turns}$$

$$= 1.9 \times 10^7 \text{ A.m per m}$$


# Critical line and magnet load lines




we expect the magnet to go resistive '*quench*' where the peak field load line crosses the critical current line \*



# 'Training' of magnets




- when the current (and field) of a magnet is ramped up for the first time, it usually 'quenches' (goes resistive) at less than the expected current
- at the next try it does better
- known as **training**



Training of LHC short prototype dipoles (*from A. Siemko*)

# Causes of training: (1) low specific heat



- the specific heat of all substances falls with temperature
- at 4.2K, it is **~2,000 times** less than at room temperature
- a given release of energy within the winding thus produce a temperature rise 2,000 times greater than at room temperature
- the smallest energy release can therefore produce catastrophic effects

# Causes of training: (2) conductor motion

- Big electromagnetic forces in magnets
- Bursting force in LHC dipoles = 320 tonne/m
- Conductors are pushed by the electromagnetic forces.
- Frictional heating if they move

work done per unit length of conductor if it is pushed a distance  $\delta z$

$$W = F \cdot \delta z = B \cdot I \cdot \delta z$$

frictional heating per unit volume

$$Q = B \cdot J \cdot \delta z$$


typical numbers for NbTi:

$$B = 5\text{T} \quad J_{\text{eng}} = 5 \times 10^8 \text{ A.m}^{-2}$$

$$\text{so if } \delta = 10 \mu\text{m}$$

$$\text{then } Q = 2.5 \times 10^4 \text{ J.m}^{-3}$$

Starting from 4.2K  $\theta_{\text{final}} = 7.5\text{K}$



can you  
engineer a  
winding to  
better than  
**10  $\mu\text{m}$ ?**





# Causes of training: (3) resin cracking

- try to stop wire movement by impregnating the winding with epoxy resin
- the resin contracts much more than the metal - so it goes into tension
- it also become brittle at low temperature.

*brittleness + tension  $\Rightarrow$  cracking  $\Rightarrow$  energy release*

## Calculate the stain energy induced in resin by differential thermal contraction

let:  $\sigma$  = tensile stress       $Y$  = Young's modulus  
 $\varepsilon$  = differential strain     $\nu$  = Poisson's ratio

thermal contraction of Cu  $\sim 3 \times 10^{-3}$  (room to 4K)

thermal contraction of resin  $\sim 11 \times 10^{-3}$


so  $\varepsilon = (11 - 3) \times 10^{-3}$

typically  $Y = 7 \times 10^9 \text{ Pa}$      $\nu = 1/3$

strain energy       $Q_1 = \frac{\sigma^2}{2Y} = \frac{Y\varepsilon^2}{2}$        $Q_1 = 2.5 \times 10^5 \text{ J.m}^{-3}$       (*uniaxial strain*)

if released adiabatically, raises temperature to

$$\theta_{final} = 16\text{K}$$



# How to reduce training?

## 1) Reduce the disturbances occurring in the magnet winding



- make the winding fit together exactly to reduce movement of conductors under field forces
- pre-compress the winding to reduce movement under field forces
- if using resin, minimize the volume and choose a crack resistant type
- match thermal contractions, eg fill epoxy with mineral or glass fibre

**most accelerator magnets are insulated using a Kapton film with a thin adhesive coating**

## 2) Make the conductor able to withstand disturbances without quenching

- increase the **temperature margin**

- increase the **minimum quench energy**



# Minimum quench energy MQE

- MQE is the smallest energy input which quenches the conductor.
- measure it by injecting short (100 $\mu$ s) heat pulses at a point on the conductor.


**large MQE**

$\Rightarrow$  **more stable conductor**

$\Rightarrow$  **less training**

**for a large MQE we need:**


- large temperature margin
- large thermal conductivity – need copper
- small resistivity – need copper
- large specific heat – difficult
- good cooling – winding porous to liquid helium coolant





# Persistent screening currents

- when a superconductor is subjected to a changing magnetic field, screening currents are induced to flow
- **screening currents** are in addition to the **transport current**, which comes from the power supply
- they are like eddy currents but, because there is no resistance, they don't decay





- usual model is a superconducting slab in a changing magnetic field  $B_y$
- assume it's infinitely long in the  $z$  and  $y$  directions - simplifies to a 1 dim problem
- $dB/dt$  induces an electric field  $E$  which causes screening currents to flow at critical current density  $J_c$
- known as the **critical state model** or **Bean model**
- in the 1 dim infinite slab geometry, Maxwell's equation says

$$\frac{\partial B_y}{\partial x} = -\mu_o J_z = \mu_o J_c$$

- so uniform  $J_c$  means a constant field gradient inside the superconductor

# The flux penetration process

plot field profile across the slab



field decreasing through zero


# Magnetization of the Superconductor

When viewed from outside the sample, the persistent currents produce a magnetic moment.

define a magnetization (magnetic moment per unit volume)


$$M = \sum_V \frac{I \cdot A}{V} \quad \text{NB units of } H$$

for a fully penetrated slab



$$M = \frac{1}{a} \int_0^a J_c x dx = \frac{J_c a}{2}$$

for **cylindrical** filaments the inner current boundary is roughly elliptical (controversial)



when fully penetrated, the magnetization is


$$M = \frac{2}{3\pi} J_c d_f$$

where  $d_f$  = filament radius

Note:  $M$  is here defined per unit volume of NbTi filament









# Magnetization of NbTi



# Coupling between filaments

recap  $M = \frac{4}{3\pi} J_c a$

- reduce M by making fine filaments
- for ease of handling, filaments are embedded in a copper matrix



- but in changing fields, the filaments are magnetically coupled
- screening currents go up the left filaments and return down the right

- fortunately the coupling currents may be reduced by twisting the wire
- coupling currents behave like eddy currents and produce an additional magnetization

$$M_e = \frac{dB}{dt} \frac{1}{\rho_t} \left[ \frac{p_w}{2\pi} \right]^2$$

where  $\rho_t$  = resistivity across the copper  
and  $p_w$  = wire twist pitch

# Coupling $\Rightarrow$ rate dependent magnetization

recap: magnetization has two components:

- persistent current in the filaments


$$M_f = \frac{2}{3\pi} J_c(B) d_f$$

**$M_f$  depends on  $B$**

- and eddy current coupling between the filaments

$$M_e = \frac{dB}{dt} \frac{l}{\rho_t} \left[ \frac{p_w}{2\pi} \right]^2$$

**$M_e$  depends on  $dB/dt$**



Note  $M_f$  defined per unit volume of NbTi filament  
and  $M_e$  per unit volume of wire

# Why cables?


- for good tracking connect synchrotron magnets in series
- if stored energy is  $E$ , rise time  $t$  and operating current  $I$ , the charging voltage is

$$E = \frac{1}{2} L I^2 \quad V = \frac{L I}{t} = \frac{2E}{I t}$$

**RHIC**  $E = 40\text{kJ/m}$ ,  $t = 75\text{s}$ , 30 strand cable  
cable  $I = 5\text{kA}$ , charge voltage per km = **213V**  
wire  $I = 167\text{A}$ , charge voltage per km = **6400V**

**FAIR at GSI**  $E = 74\text{kJ/m}$ ,  $t = 4\text{s}$ , 30 strand cable  
cable  $I = 6.8\text{kA}$ , charge voltage per km = **5.4kV**  
wire  $I = 227\text{A}$ , charge voltage per km = **163kV**




- so we need high currents!
- a single  $5\mu\text{m}$  filament of NbTi in 6T carries 50mA
- a composite wire of fine filaments typically has 5,000 to 10,000 filaments, so it carries 250A to 500A
- for 5 to 10kA, we need 20 to 40 wires in parallel - **a cable**



*the RHIC tunnel*

# Rutherford cable

- fully transposed - every strand changes places with every other
- cable insulated by wrapping 2 or 3 layers of Kapton
- gaps may be left to allow penetration of liquid helium
- outer layer is treated with an adhesive layer for bonding to adjacent turns.






# Coupling in Rutherford cables


- Field transverse

coupling via crossover resistance  $R_c$




crossover resistance  $R_c$

adjacent resistance  $R_a$



- Field transverse

coupling via adjacent resistance  $R_a$



$$M_{tc} = \frac{1}{120} \frac{\dot{B}_t}{R_c} p \frac{c}{b} N(N-1)$$

$$M_{ta} = \frac{1}{6} \frac{\dot{B}_t}{R_a} p \frac{c}{b}$$

(Field parallel gives much smaller coupling via adjacent resistance  $R_a$ )


# Cable coupling adds more magnetization

filament magnetization  $M_f$  depends on  $B$

$$M_f = \frac{2}{3\pi} J_c(B) d_f$$

coupling between filaments  $M_e$  depends on  $dB/dt$

$$M_e = \frac{dB}{dt} \frac{l}{\rho_t} \left[ \frac{p_w}{2\pi} \right]^2$$



coupling between wires in cable depends on  $dB/dt$


$$M_{tc} = \frac{l}{120} \frac{\dot{B}_t}{R_c} p \frac{c}{b} N(N-1)$$

$$M_{ta} = \frac{l}{6} \frac{\dot{B}_t}{R_a} p \frac{c}{b}$$

# Magnetization and field errors


Magnetization is important in accelerators because it produces field error. The effect is worst at injection because

- $\Delta B/B$  is greatest
- magnetization, ie  $\Delta B$  is greatest at low field




*skew  
quadrupole  
error in  
Nb<sub>3</sub>Sn dipole  
which has  
exceptionally  
large  
coupling  
magnetization  
(University of  
Twente)*


# Synchrotron injection



- synchrotrons inject at low field, ramp to high field and then down again




- note how quickly the magnetization changes when we start the ramp up



- much less magnetization change if we ramp down to zero and then up to injection

# AC losses



For a magnet material, work done by magnetic field

$$dW = \mu_o H dM$$

around a closed loop

$$W = \int \mu_o H dM$$

loop comes back to same place

- field energy is same  
- so work done is ac loss in material

ac loss is area of hysteresis loop

$$W = \int \mu_o H dM = \int \mu_o M dH$$



# Magnetic stored energy

**Magnetic energy density**  $E = \frac{B^2}{2\mu_0}$  at 5T  $E = 10^7 \text{ Joule.m}^{-3}$  at 10T  $E = 4 \times 10^7 \text{ Joule.m}^{-3}$

**LHC dipole magnet (twin apertures)**  $E = \frac{1}{2}LI^2$   $L = 0.12\text{H}$   $I = 11.5\text{kA}$   $E = 7.8 \times 10^6 \text{ Joules}$

the magnet weighs 26 tonnes

so the magnetic stored energy is equivalent to the kinetic energy of:-


**26 tonnes travelling at 88km/hr**




coils weigh 830 kg

equivalent to the kinetic energy of:-

**830kg travelling at 495km/hr**



# The quench process



- resistive region starts somewhere in the winding at a **point**  
- **this is the problem!**
- it grows by thermal conduction
- stored energy  $\frac{1}{2}LI^2$  of the magnet is dissipated as heat
- greatest integrated heat dissipation is at point where the quench starts
- internal voltages much greater than terminal voltage ( $= V_{cs}$  current supply)
- maximum temperature may be calculated from the current decay time via the  $U(\theta)$  function (adiabatic approximation)

# The temperature rise function $U(\theta)$

or the 'fuse blowing' calculation  
(adiabatic approximation)

$$J^2(T)\rho(\theta)dT = \gamma C(\theta)d\theta$$

$J(T)$  = overall current density,

$T$  = time,

$\rho(\theta)$  = overall resistivity,

$\gamma$  = density,  $\theta$  = temperature,


$C(\theta)$  = specific heat,

$T_Q$  = quench decay time.

$$\int_0^\infty J^2(T)dT = \int_{\theta_0}^{\theta_m} \frac{\gamma C(\theta)}{\rho(\theta)} d\theta$$
$$= U(\theta_m)$$


$$J_o^2 T_Q = U(\theta_m)$$

- GSI 001 dipole winding is  
50% copper, 22% NbTi,  
16% Kapton and 3% stainless steel




- NB always use **overall** current density

# Measured current decay after a quench




*Dipole GSI001 measured at Brookhaven National Laboratory*

# Calculating the temperature rise from the current decay curve






# *Growth of the resistive zone*



the quench starts at a point and then grows  
in three dimensions via the combined  
effects of Joule heating and  
thermal conduction

# Quench propagation velocity

- resistive zone starts at a point and spreads along the conductor and transverse to it
- the force driving it forward is the heat generation in the resistive zone, together with heat conduction along the wire




## Along the conductor

$$v_{long} = \frac{J}{\gamma C} \left\{ \frac{\rho k}{\theta_t - \theta_0} \right\}^{\frac{1}{2}}$$

where:  $J$  = engineering current density,  $\gamma$  = density,  $C$  = specific heat,  $\rho$  = resistivity,  $k$  = thermal conductivity,  $\theta_t$  = transition temperature

## Transverse to the conductor

$$\alpha = \frac{v_{trans}}{v_{long}} = \left\{ \frac{k_{trans}}{k_{long}} \right\}^{\frac{1}{2}}$$



**Typical values**

$$v_{ad} = 5 - 20 \text{ ms}^{-1}$$

$$\alpha = 0.01 - 0.03$$

# Computation of resistance growth and current decay


start resistive zone 1

in time  $\delta t$  zone 1 grows  $v \cdot dt$  longitudinally and  $\alpha \cdot v \cdot dt$  transversely


temperature of zone grows by  $\delta\theta_1 = J^2 \rho(\theta_1) \delta\tau / \gamma C(\theta_1)$

resistivity of zone 1 is  $\rho(\theta_1)$

calculate resistance and hence current decay  $\delta I = R / L \cdot \delta t$



in time  $\delta t$  add zone n:  
 $v \cdot \delta t$  longitudinal and  $\alpha \cdot v \cdot \delta t$  transverse



temperature of each zone grows by  $\delta\theta_1 = J^2 \rho(\theta_1) \delta t / \gamma C(\theta_1)$   $\delta\theta_2 = J^2 \rho(\theta_2) \delta t / \gamma C(\theta_2)$   $\delta\theta_n = J^2 \rho(\theta_n) dt / \gamma C(\theta_n)$


resistivity of each zone is  $\rho(\theta_1)$   $\rho(\theta_2)$   $\rho(\theta_n)$  resistance  $r_1 = \rho(\theta_1) * f_{g1}$  (geom factor)  $r_2 = \rho(\theta_2) * f_{g2}$   $r_n = \rho(\theta_n) * f_{gn}$

calculate total resistance  $R = \sum r_1 + r_2 + r_n \dots$  and hence current decay  $\delta I = (I R / L) \delta t$

when  $I \Rightarrow 0$  stop


# Methods of quench protection:

## 1) External dump resistor



- detect the quench electronically
- open an external circuit breaker
- force the current to decay through the resistor

## 2) Quench back heater



*method most commonly used in accelerator magnets ✓*

- detect the quench electronically
- power a heater in thermal contact with the winding
- this quenches other regions of the magnet, forcing the normal zone to grow more rapidly
  - ⇒ higher resistance
  - ⇒ shorter decay time
  - ⇒ lower temperature rise at the hot spot



# *Winding an LHC dipole*



*photo courtesy of Babcock Noell*




# *Curing press*




# Collars

How to make an external structure that


- fits tightly round the coil
  - presses it into an accurate shape
  - has low ac losses
  - can be mass produced cheaply
  - ???
- Answer make collars by precision stamping of stainless steel or aluminium alloy plate a few mm thick
  - inherited from conventional magnet laminations



*press collars over coil from above and below*




*invert alternate pairs so that they interlock*




*push steel rods through holes to lock in position*

# Collars and end plate (LHC dipole)







# Adding the iron



- they are forced into place, again using the collaring press
- remember however that pure iron becomes brittle at low temperature
- the tensile forces are therefore taken by a stainless steel shell which is welded around the iron, while still in the press
- this stainless shell can also serve as the helium vessel




# *Dipole inside its stainless shell*






# Complete magnet in cryostat





# *Make a lot of Magnets and install in the tunnel*



# Concluding remarks

- superconductivity offers higher magnetic fields and field gradients, with less energy dissipation
- NbTi is the most common superconducting material and has been used in all accelerators to date
- superconducting magnets do not use iron to shape the field, so must use special winding shapes
- magnets don't reach their expected current/field first time but show training
  - control training by reducing movement, attention to contraction and increasing MQE
- persistent screening currents produce magnetization of the superconductor which causes field errors and ac loss – need fine  $\sim 5\mu\text{m}$  filaments
- accelerators need high currents, so must use many wires in parallel – a cable
- coupling between filament in wire and between wires in cable increases magnetization
- magnets store large inductive energy which is released at quench as heating – must protect
- magnet manufacturing techniques have been developed to ensure accurate winding shape and minimize conductor movement

customer support: [m-wilson@dsl.pipex.com](mailto:m-wilson@dsl.pipex.com)

# Some useful references

## Superconducting Magnets

- Superconducting Accelerator Magnets: KH Mess, P Schmuser, S Wolf., pub World Scientific, (1996) ISBN 981-02-2790-6
- High Field Superconducting Magnets: FM Asner, pub Oxford University Press (1999) ISBN 0 19 851764 5
- Case Studies in Superconducting Magnets: Y Iwasa, pub Plenum Press, New York (1994), ISBN 0-306-44881-5.
- Superconducting Magnets: MN Wilson, pub Oxford University Press (1983) ISBN 0-019-854805-2
- Proc Applied Superconductivity Conference: pub as IEEE Trans Applied Superconductivity, Mar 93 to 99, and as IEEE Trans Magnetism Mar 75 to 91
- Handbook of Applied Superconductivity ed B Seeber, pub UK Institute Physics 1998
- JUAS lectures on superconducting magnets (and all accelerator topics) <http://juas.in2p3.fr>
- 'Superconducting Accelerator Magnets' DVD available from [mjball @ comcast.net](mailto:mjball@comcast.net)

## Superconducting Materials

- Superconductor Science and Technology, published monthly by Institute of Physics (UK).
- Superconductivity of metals and Cuprates, JR Waldram, Institute of Physics Publishing (1996) ISBN 0 85274 337 8
- High Temperature Superconductors: Processing and Science, A Bourdillon and NX Tan Bourdillon, Academic Press, ISBN 0 12 117680 0

## Materials Mechanical

- Materials at Low Temperature: Ed RP Reed & AF Clark, pub Am. Soc. Metals 1983. ISBN 0-87170-146-4
- Handbook on Materials for Superconducting Machinery pub Batelle Columbus Laboratories 1977.
- Nonmetallic materials and composites at low temperatures: Ed AF Clark, RP Reed, G Hartwig pub Plenum
- Nonmetallic materials and composites at low temperatures 2, Ed G Hartwig, D Evans, pub Plenum 1982
- Austenitic Steels at low temperatures Editors R.P.Reed and T.Horiuchi, pub Plenum 1983

## Cryogenics

- Helium Cryogenics Van Sciver SW, pub Plenum 86 ISBN 0-0306-42335-9
- Cryogenic Engineering, Hands BA, pub Academic Press 86 ISBN 0-012-322991-X
- Cryogenics: published monthly by Butterworths
- Cryogenie: Ses Applications en Supraconductivite, pub IIR 177 Boulevard Malesherbes F5017 Paris France

# Materials data web sites

- Cryogenic properties (1-300 K) of many solids, including thermal conductivity, specific heat, and thermal expansion, have been empirically fitted and the equation parameters are available free on the web at [www.cryogenics.nist.gov](http://www.cryogenics.nist.gov)
- Plots and automated data-look-up using the NIST equations are available on the web for a fee from [www.cpia.jhu.edu](http://www.cpia.jhu.edu)
- Other fee web sites that use their own fitting equations for a number of cryogenic material properties include: [www.cryodata.com](http://www.cryodata.com) (cryogenic properties of about 100 materials), and [www.jahm.com](http://www.jahm.com) (temperature dependent properties of about 1000 materials, many at cryogenic temperatures).
- Commercially supplied room-temperature data are available free online for about 10 to 20 properties of about 24,000 materials at [www.matweb.com](http://www.matweb.com)

*thanks to Jack Ekin of NIST for this information*

## *Cryodata Software Products*

### GASPAK

properties of pure fluids from the triple point to high temperatures.

### HEPAK

properties of helium including superfluid above 0.8 K, up to 1500 K.

### STEAMPAK

properties of water from the triple point to 2000 K and 200 MPa.

### METALPAK, CPPACK, EXPAK

reference properties of metals and other solids, 1 - 300 K.

### CRYOCOMP

properties and thermal design calculations for solid materials, 1 - 300 K.

### SUPERMAGNET

four unique engineering design codes for superconducting magnet systems.

### KRYOM

numerical modelling calculations on radiation-shielded cryogenic enclosures.