



FAILURES AND MISCONCEPTIONS

FAILURES AND MISCONCEPTIONS

- **AIM OF THE TALK**

- DESCRIBE FAILURES
- SHOW THEIR ORIGIN (MISCONCEPTIONS)
- DETERMINE WHAT WAS WRONG
- DRAW ATTENTION ON BEHAVIOR/PROCEDURES LEADING TO FAILURE

- **CONTENT**

- OPERATION EXAMPLES
- THE LHC BELLOWS
- CORROSION

- **THANKS**

- *TO MY COLLEAGUES FOR THEIR HELP IN COMPLETING THAT PRESENTATION:*
- *THE METALLURGICAL SECTION :S. SGOBBA, JP BACHER, G. ARNAU*
- *C. HAUVILLER, M. JIMEMEZ, P.STRUBIN, K. ZAPFE*

OPERATION

- **GREAT VARIETY OF PROBLEMS**

- **FAULTY COMPONENTS**

- **PROCEDURES AND CONTROL**

- **EXAMPLES**

- **THE SPS SUPERCONDUCTING CAVITY**

- **THE LEP ENERGY UPGRADE**


- **MISCELLANEOUS**

OPERATION

• THE SPS SC. CAVITY:

–THE EVENTS

- *0 mn VACUUM ALARM: ION PUMPS SWITCHED OFF AND SECTOR VALVES CLOSED*
- *12 mn LATER: CRYO ALARM: COMPRESSOR STOPPED*
- *35 mn :ALARM LOW He IN CAVITY*
- *39 mn : VACUUM ALARM SECTOR VALVES CLOSED AROUND CAVITY*



CONSEQUENCES


- *AFTER COOL DOWN CAVITY HAS LOST RESONANCE!*
- *RECOVERED AFTER COMPLETE WARM UP AND RECOOLING (CONDENSED GAS THICKNESS)*

OPERATION

- **THE SPS SC. CAVITY:**

- ANALYSIS

- *THE PROTON BEAM MADE A HOLE IN THE VACUUM CHAMBER*
 - *SOME VALVES CLOSED, NOT THOSE BETWEEN THE HOLE AND THE CAVITY (NEEDS 3 BAD ION PUMP SIGNALS)*
 - *FINALLY WHEN THE LIQUID HELIUM LEVEL WAS LOST THE SECTOR VALVES AFTER THE CAVITY CLOSED AND AVOIDED FURTHER PROPAGATION*



OPERATION

- **THE SPS SC. CAVITY:**

- **FAULTS AND REMEDIES**

- *FOR HISTORICAL REASONS INTERLOCKS WERE SET AT MAXIMUM (P.P., 80^{IES}), A 3S DELAY WAS INTRODUCED TO ELIMINATE FALSE TRIGGERS*
 - *AGING POWER SUPPLIES :
NO MORE ABLE TO DELIVER FULL CURRENT =>
=> INTERLOCK LEVEL NO MORE REACHABLE*
 - *FAST VALVES WERE OPENED DESPITE BAD PRESSURE*

OPERATION

• THE SPS SC. CAVITY:

–LESSONS


- *INTERLOCK LEVELS DEPENDS ON THE OPERATION CONDITIONS*
- *THEY MUST BE PERIODICALLY REVIEWED AND KEPT TO A MINIMUM COMPATIBLE WITH SAFE OPERATION*
- *TOO MANY INTERLOCKS => BY-PASS*
- *A BY-PASSED INTERLOCK IS MORE DANGEROUS THAN NO INTERLOCK*

OPERATION

• THE LEP ENERGY UPGRADE:




–GRADUAL ENERGY INCREASE

- *FROM 45 GEV (1989) TO 100 GEV (1999)
(i.e. 40->1000 W/m)*
- *SOME COMPONENTS DESIGNED FOR 45 GEV
FORGOTTEN
(UNCOOLED TRANSITIONS ELLIPTICAL->
CIRCULAR)*
- *INAPPROPRIATE FOR USE ABOVE 90 GEV
(SYNCHROTRON LIGHT POWER)*
- *MANY FAILURES:*
 - OVERHEATED CF GASKETS
 - WELD FAILURES (REPEATED THERMAL CYCLES)



OPERATION

- **THE LEP ENERGY UPGRADE:**
 - **WELD FAILURES:**
 - **CLASSIC WELD**
304 L TUBE / 316 LN FLANGE



OPERATION


• THE LEP ENERGY UPGRADE:

–ORIGIN


- *FORGOTTEN WEAK ELEMENT*
+
- *IMPROPER WELD PREPARATION:
MASSIVE <-> THIN PIECES*

- *=> LACK OF PENETRATION FOR THE
MASSIVE PART*

- *WELDING LIPS PREFERABLE*



TUBE TUBE



OPERATION

• **THE LEP ENERGY UPGRADE:**

–**LESSONS:**

- *PROVISIONAL IS DANGEROUS AND MUST BE TRACED*
- *WELL ORGANISED DATABASE OF COMPONENTS :
=>EASY TO FIND PIECES WITH SIMILAR GEOMETRIES*
- *STANDARDISATION OF ESTABLISHED GOOD PRACTICE/RECEPIES
e.g. FOR WELD GEOMETRY*

AND IMPOSE THEIR USE

OPERATION

• VENTING

–TYPICAL CASE

- *ROUTINE ACTIVITY*
- *CONSIDERED AS SIMPLE (OBVIOUS!!)*

–BUT...

- *COULD HELP YOU TO BECOME (VERY) POPULAR*
- *NUMEROUS EXAMPLES IN ALL ACCELERATORS OF MISHAPS*
- *COULD BECOME EXTREMELY EXPENSIVE :
(DEMOUNTING/RINSING A SC MODULE)*

–COMMON ERRORS

- *WRONG PLACE (SECTOR)*
- *WRONG PRESSURE (COULD BE SPECTACULAR ON BELLOWS!)*
- *WRONG FLUX FOR CRITICAL COMPONENTS (DUST FREE PLACES, LARGE ELECTRODES...)*

OPERATION

• VENTING

– LESSONS

- *PROPER LABELING OF VENTING VALVES*
- *COLLEAGUES CHECKING THE PRESSURE IN ADJACENT SECTORS DURING THE VENTING*
- *CAREFUL START OF GAS INJECTION : CHECK PRESSURE IN ADJACENT SECTORS*
- *TEAMS INFORMED OF ANOMALIES IN THE SECTORISATION (SECTOR VALVES BLOCKED OPEN)*
- *RELIABLE PRESSURE LIMITING SYSTEM (COULD BE AS SIMPLE AS A KF FLANGE WITHOUT COLLAR!)*

BELLOWS FAILURE

- **COURTESY C. HAUVILLER**

- **THE LHC CRYOGENIC LINE**

- *LARGE COLLIDER OPERATING AT 1.9K*

- *LIQUID HELIUM FEED*

- **FLEXIBLE ELEMENTS**

- *ALIGNMENT*

- *THERMAL MOVEMENTS (room temperature)*



N. HILLERET

Failures and misconceptions

BELLOWS FAILURE

• BELLOWS DESIGN


– Design:

- *Mainly for alignment:*
- => “cardan design”
- *Limited temperature variation*

– Construction

- *4 large undulations (flexibility)*
- *Rigid spacer*

–For economical reasons:
spacer same material/thickness
=>Undulations needed for rigid.
Nominal height 15mm



BELLOWS FAILURE

• STABILITY CALCULATIONS

–Calculated according to ASME code

Straight Pipe Under External Pressure

Center connector

Moment of inertia:

$$\begin{aligned} I_{\text{connector}} &= 14562 \text{ mm}^4 \\ L &= 570 \text{ mm} \\ t_{\text{pipe}} &= 6.7 \text{ mm (equivalent pipe thickness)} \\ p_d &= 1 \text{ bar} \\ T &= 20 \text{ C (68 F)} \\ D_o &= 734 \text{ mm} \\ t &= 6.7 \text{ mm} \\ L / D_o &= 0.777 \text{ -} \\ D_o / t &= 108.86 \text{ -} \end{aligned}$$

Factors :

$$\begin{aligned} A &= 0.0132 \text{ - Fig. G; ASME II, Part D, Subpart 3} \\ B &= 15000 \text{ - Fig. HA-1; ASME II, Part D, Subpart 3 (ALLOY 316)} \end{aligned}$$

$$p_a = \frac{4 \cdot B}{3 \cdot \left(\frac{D_o}{t}\right)} =$$


12.67 bar

$$p_d = 1 \text{ bar} <$$

BELLOWS FAILURE

- **RESULTS**

- Initial installation without problem
- Collapses after impacts
- But later without external intervention






BELLOWS FAILURE

• ANALYSIS

–CONVOLUTIONS TOO SMALL :

- *NOMINAL 15mm*
- *MEASURED 8 mm*
- *DRIFT DURING THE PRODUCTION (TOOLING)*



BELLOWS FAILURE

- **CURE**


- 2 REINFORCEMENT RINGS

- **ORIGIN**

- *INAPPROPRIATE CODE FOR CALCULATIONS (thin walls)*

- *UNMONITORED DRIFT DURING FABRICATION*

- *Note: PRODUCED BY A SUB-CONTRACTOR OF THE MAIN CONTRACTOR*



BELLOWS FAILURE

- **LESSONS**

- BYING “TURN KEY” SYSTEM IS NOT AS SIMPLE AS FORESEEN

- HENCE A CAREFUL FOLLOW UP OF PRODUCTION IS MANDATORY EVEN AT THE STAGE OF COMPONENTS

- THE QUALITY PLAN OF THE CONTRACTOR MUST BE CHECKED

- COMMON INSPECTIONS MUST BE MADE AT THE SUBCONTRACTORS

CORROSION

- **A LONG STORY IN ACCELERATORS**

- **MILD MEDIUM**

- *PROTECTED AGAINST AGGRESSIVE MEDIA (limited humidity)*
 - *NO AGGRESSIVE AGENTS (O_3 Nox. EXCEPTED) ALLOWED*

- **RESISTANT MATERIALS :**

- *STAINLESS STEELS*
 - *ALUMINUM*
 - *COPPER*

- **BUT....**

- **NUMEROUS EXAMPLES IN ALL MACHINES**

- **CAUSES KNOWN SINCE LONG**


- **ALWAYS REAPPEARING**

.....**SOMETIMES FOR IDENTICAL REASONS !!**

CORROSION

- **FIRST BELLOW STORY:
ISR SUMMER 1980**

- *LEAK ON A QUAD CHAMBER (BELLOW) INSTALLED FOR 1 YEAR*
- *MATERIAL ST. STEEL 316 L*
- *HEAVY OXIDATION VISIBLE WHERE THE BELLOWS WAS ACCESSIBLE*




CORROSION

- **FIRST BELLOW STORY: ISR**
(COURTESY J.P. BACHER)

- *LEAK FROM OUTSIDE*

- *CLOSER....*


- *AND FROM INSIDE*



CORROSION

- **ISR BELLOW: ORIGIN OF FAILURE**

- *CULPRIT HAS LEFT TRACES*
- *CORROSION BY BRAZING FLUX (*ZnCl₂)*
- *ST. STEEL EXTREMELY SENSITIVE TO
Cl PITTING*




**–BRAZING ACTIVITIES WITHOUT PROTECTION
(and care) ON ADJACENT MAGNET**

CORROSION

• THE SPS HORROR SHOW (COURTESY M. JIMENEZ)

–400 GeV SYNCHROTRON (LHC INJECTOR)

- *FIXED TARGET PHYSICS*
- *HIGH RADIATION AREA (5×10^5 Gray/year)*
- *ALL ST. STEEL CONSTRUCTION (304 L)*



N. HILLERET

Failures and misconceptions

25

CAS Platja d'Aro

16-24/05/06

CORROSION

- **THE SPS HORROR SHOW**

–SEEN FROM “RADIATION SAFE” DISTANCE:

- *NORMAL*

- **BUT.....**



CORROSION

- **THE SPS HORROR SHOW**

 - CLOSER**



21

CORROSION

THE SPS HORROR SHOW

- OTHER EXAMPLES

-



CORROSION

• THE SPS HORROR SHOW

–VERY COSTLY:

- *TIME LOST FOR EXPERIMENTS*
- *MORE THAN 25 INTERVENTIONS OF THE VACUUM PIQUET IN 6 WEEKS (>4/WEEK!)*
- *HIGH RADIATION ZONE ⇒ 27 PEOPLES INVOLVED SHARING 21 mSv*
- *REPLACEMENT OF A COMPLETE SECTOR (30 m)*
 - » *13 CHAMBERS AND 14 BELLOWS MANUFACTURED AND EXCHANGED IN ONLY 5 DAYS*
- *CHAMBERS PROTECTED BY ALUMINUM FOIL*



N. HILLERET

Failures and misconceptions

CAS Platja d'Aro

16-24/05/06

CORROSION

- **THE SPS HORROR SHOW: ORIGIN**


–MOST DAMAGES ON TOP OF COMPONENTS: CABLE TRAY

–NOTE DISCOLORATION!!




CORROSION

• THE SPS HORROR SHOW: ORIGIN






**–THE FIRE DETECTION PIPE
WAS MADE OF PVC!!!**



CORROSION

• THE LEP BELLOWS:

- *A bellows in LEP injection region (high radiation area)*
- *Leak position:*
- *Presence of chlorine*




CORROSION

• THE LEP BELLOWS: ORIGIN

- *SIGNAL NEEDED FOR THE INJECTION TIMING*
- *TRIGGER GIVEN BY A PHOTOMULTIPLIER*
- *TRANSPARENCY \Leftrightarrow MORE SENSITIVITY*
- *=> BELLOWS IDEAL*
- *PHOTOMULTIPLIER AS CLOSE AS POSSIBLE TO THE BEAM*
- *=> TOUCHING THE BELLOW*

-BUT

- *THE ADHESIVE BLACK TAPE AROUND THE PHOTOMULTIPLIER CONTAINED CHLORINE (PVC BASED)!*



CORROSION

- **LESSONS**



FAILURES AND MISCONCEPTIONS

• CONCLUSIONS

- DESCRIBED FAILURES ORIGINATE FROM WELL KNOWN MISCONCEPTIONS
- EVERY FAILURE MUST BE INVESTIGATED, EXPLAINED AND RECORDED
- GOOD PRACTICE DIFFICULT TO INTRODUCE BEFORE FAILURE
- HABITS (EVEN BAD) TEND TO PERPETUATE:
 - *“ONE HAS ALWAYS DONE LIKE THIS”*
- “TURN KEY SYSTEMS” ARE VERY DIFFICULT TO CONTROL

FAILURES AND MISCONCEPTIONS

CONCLUSIONS

**–DEVELOP INTERNAL STANDARDS FOR ENGINEERING
AND CRITICAL PRODUCTION/OPERATION STEPS
(e.g. WELDING, CLEANING, VENTING, BAKING...)**

...AND HAVE THEM APPLIED!!

**–PERIODIC REVIEW OF LAYOUTS, PROCEDURES AND
INTERLOCKS TO ELIMINATE OBSOLETE (DANGEROUS)
SITUATION**

***• A GOOD WALK IN THE ACCELERATOR IS HEALTHY
FOR THE SUPERVISOR
AND.. THE ACCELERATOR***

A black and white photograph showing a ship's deck. Large pieces of equipment are covered with dark, wrinkled tarps. A person in a light-colored uniform is visible in the background, looking towards the camera. The scene is filled with various pipes, cables, and structural elements of the ship. Overlaid on the center of the image is the text "THANK YOU FOR YOUR ATTENTION" in a bold, red, serif font.

THANK YOU FOR YOUR ATTENTION